Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	4	("5255146" "5400202" "5463520" "5528188").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2006/07/06 06:26
L2	43	(disable disabling disabled) near3 (RC near2 delay RC near2 timer RC near2 detection RC near2 circuit)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/06 08:39
L3	132	reset and (RC near2 delay RC near2 timer RC near2 detection RC near2 circuit) and ESD	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/06 06:34
L4	3	("5559659" " 64 34061" "6552886").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2006/07/06 06:30
L5	165	feedback and (RC near2 delay RC near2 timer RC near2 detection RC near2 circuit) and ESD	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/06 06:34
L6	6	("5012317" "5465189" "6016002" "6172404" "6541801" "6542346").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2006/07/06 06:44
L7	3	("5400202" "5463520" "5528188").PN.	US-PGPUB; USPAT; USOCR	OR	ON	-2006/07/06 06:45
L8	5	("5835328").URPN.	USPAT	OR	ON	2006/07/06 06:46
L9	2	("4766334" "5255146").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2006/07/06 06:53
L10	17	("5559659").URPN.	USPAT	OR	ON	2006/07/06 06:53
L11	12	("20030201457" "20040136126" "5255146" "5559659" "5744842" "5745323" "5946177" "6118640" "6242942" "6552511" "6552583" "6552886").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2006/07/06 06:54
L12	9	("5239440" "5345357" "5508649" "5559659" "5610790" "5838146" "5907464" "5946177" "5956219").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2006/07/06 07:08
L13	1	("6369994").PN.	US-PGPUB; USPAT	OR	OFF	2006/07/06 07:08
L14	16	("4423431" "4819047" "4989057" "5124877" "5311391" "5489792" "5528188" "5567968" "5591992" "5610790" "5625214" "5683918" "5708288" "5726844" "5729419" "5811857").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2006/07/06 07:11
L15	13	("4385337" "4763184" "4868705" "4870530" "4876584" "4930036" "4996626" "5012317" "5028819" "5059831" "5060037" "5086365" "5237395").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2006/07/06 07:13
L16	32	("5311391").URPN.	USPAT	OR	ON	2006/07/06 07:13
L17	11	("4855620" "5086365" "5237395" "5255146" "5287241" "5311391" "5440162" "5610791" "5625280" "5631793" "6008970").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2006/07/06 07:14

			-			
L18	17	("4595941" "4835416" "4890187" "4918563" "4922371" "4978867" "4980792" "4982113" "5041889" "5121007" "5124578" "5134314" "5189588" "5239440" "5287241" "5343352" "5345357").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2006/07/06 07:16
L19	11	("5625280").URPN.	USPAT	OR	ON	2006/07/06 08:07
L20	1	("5535086").PN.	US-PGPUB; USPAT	OR	OFF	2006/07/06 08:09
L21	0	(2004/0083315).CCLS.	US-PGPUB; USPAT	OR	OFF	2006/07/06 08:09
L22	0	2004/0083315	US-PGPUB; USPAT	OR	ON	2006/07/06 08:09
L23	1	"20040083315"	US-PGPUB; USPAT	OR	ON	2006/07/06 08:38
L24	3294	(361/56-58).CCLS.	US-PGPUB; USPAT	OR	OFF	2006/07/06 08:38
L25	199	24 and (RC near2 delay RC near2 timer RC near2 detection RC near2 circuit)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/06 08:39
L26	31	(disable disabling disabled override) and 25	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/06 08:40
L27	43	(disable disabling disabled override reset) and 25	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/06 08:40
S1	1	("6385021").PN.	US-PGPUB; USPAT	OR	OFF	2006/07/03 12:00
S2	10	("5311391" "5361185" "5610790" "5721656" "5751051" "5825600" "5946177" "5991134" "6002156" "6222710").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2006/07/03 11:45
S3	6	("5239440" "5287241" "5440162" "5559659" "5654862" "5745323").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2006/07/03 11:51
S4	2	("4766334" "5255146").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2006/07/03 11:52
S5	4	("4363068" "4692834" "4787007" "4890187").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2006/07/03 11:52
S6	20	("5255146").URPN.	USPAT	OR .	ON	2006/07/03 11:53
S7	12	("20030201457" "20040136126" "5255146" "5559659" "5744842" "5745323" "5946177" "6118640" "6242942" "6522511" "6552583" "6552886").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2006/07/03 11:57
S8	1	10/723965	US-PGPUB; USPAT; USOCR	OR	ON	2006/07/03 11:57
S9	1	("5946177").PN.	US-PGPUB; USPAT	OR	OFF	2006/07/03 12:03

					т	
S10	0	("durationnear3timeandESD").PN.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/07/03 12:04
S11	577	duration near3 time and ESD	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/03 13:14
S12	201	S11 and latch	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/03 12:05
S13	74	NAND same ESD	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/03 12:13
S14	17	("4595941" "4835416" "4890187" "4918563" "4922371" "4978867" "4980792" "4982113" "5041889" "5121007" "5124578" "5134314" "5189588" "5239440" "5287241" "5343352" "5345357").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2006/07/03 12:16
S15	579	(latch latching) near2 (circuit device) and ESD	US-PGPUB; USPAT; USOGR;—— EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/03 12:25
S16	49	S15 and (RC near2 delay RC near2 timer RC near2 detection RC near2 circuit)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/06 06:27
S17	96	(latch latching) near2 time and ESD	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/03 12:43
S18	952	(disable disabling) near2 (circuit device) and (RC near2 delay RC near2 timer RC near2 detection RC near2 circuit)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/03 12:43
S19	16	S18 and ESD	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/03 12:43
S20	5	("5239440" "5708549" "5734186" "5978192" "6125021").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2006/07/03 12:44

	_					
S21	1	("5463520").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2006/07/03 12:47
S22	18	("5978192").URPN.	USPAT	OR	ON	2006/07/03 12:48
S23	2	("5508649" "5978192").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2006/07/03 12:49
S24	0	("6919602").URPN.	USPAT	OR	ON	2006/07/03 12:49
S25	0	duration near3 time and (prevent\$3 near3 latch near2 up) and ESD	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/03 13:15
S26	64	duration near3 time and latch near2 up and ESD	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/03 13:18
S27	84	("3819986" "4005342" "4039869" "4061928" "4066918" "4186418" "4288829" "4366522" "4385337" "4400711" "4408245" "4456940" "4509067" "4567500" "4580063" "4605980" "4630162" "4631567" "4633283" "4678950" "4692834" "4698720" "4739378" "4811155" "4819047" "4829350" "4835653" "4839768" "4855620" "4858055" "4868705" "4870530" "4896243" "4930036" "4939616" "4949212" "4996626" "5034845" "5051860" "5086365" "5144519" "5157573" "5159518" "5196981" "5200876" "5208719" "5218506" "5237395" "5239440" "5268588" "5272586" "5276582" "5287241" "5289334" "5291051" "5291365" "5343352" "5311391" "5319259" "5333093" "5335134" "5343352" "5340202" "5406105" "5412527" "54520867" "5426323" "5430595" "5440162" "5473500" "5477413" "5477414" "5479039" "5475118" "5514893").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2006/07/03 13:17
S28	453	duration same ESD	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/03 13:26
S29	67	S28 and (RC near2 delay RC near2 timer RC near2 detection RC near2 circuit)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/03 13:18
S30	2	("5508649" "5978192").PN.	US-PGP UB; USPAT; USOCR	OR	ON	2006/07/03 13:20
S31	19	("4107556" "4254347" "4558233" "4633107" "4888497" "4922133" "4970408" "5051611" "5111067" "5136181" "5159206" "5180926" "5200648" "5237395" "5239440" "5255146" "5311391" "5323067" "5349559").PN.	US-PGP UB; USPAT; USOCR	OR	ON	2006/07/03 13:23

Selection RC near2 circuit RC USPAT; USPA				-	,	,	
S34 306 361/56.cds. and (RC near2 delay RC near2 timer RC near2 USACR; EPO; JPO; DERWENT?; IBM_TDB US-PGPUB; USOCR; EPO; JPO; DERWENT?; IBM_TDB US-PGPUB; US-PGPUB	\$32	21140		USPAT; USOCR; EPO; JPO; DERWENT;	OR	ON	2006/07/03 13:31
	S33	149	S32 and duration and ESD	USPAT; USOCR; EPO; JPO; DERWENT;	OR	ON	2006/07/03 13:27
	534	306		USPAT; USOCR; EPO; JPO; DERWENT;	OR	ON	2006/07/03 13:31
S37 1 ("5400202"),PN. US-PGPUB; USPAT; USOCR; USPAT; USOCR USPAT OR ON 2006/07/03 13:44 US-PGPUB; US-P	S35	16	"5489792" "5528188" "5567968" "5591992" "5610790" "5625214" "5683918" "5708288" "5726844"	USPAT;	OR	ON	2006/07/03 13:42
S38 7 ("6233130").URPN.	S36	4	("6369994").URPN.	USPAT	OR	ON	2006/07/03 13:42
S39 4 ("5400202" "5530612" "5543650" "5654862").PN. US-PGPUB; USPAT; USOCR. US	S37	1	("5400202").PN.	USPA T;	OR	ON	2006/07/03 13:44
S39 4 ("5400202" "5530612" "5543650" "5654862").PN. US-PGPUB;	S38	7	("6233130").URPN.	USPAT	OR	ON	2006/07/03 13:45
S40	S39	4		USPA T ;		ON	I+
Sed and (RC near2 delay RC near2 timer RC near2 detection RC near2 detection RC near2 circuit) US PGPUB; USPAT; USOCR; EPO; JPO; DET.WENT; T'E _TDB OR US.PGPUB; USCAT; USC.CR; EPO; JPO; DERWENT; USC.CR; E	S40	4	yn i	US-PG PUB ; USPAT;		ON	2006/07/03 13:56
S42 S69 esd and (RC near2 delay RC near2 timer RC near2 detection RC near2 detection RC near2 circuit) US PGPUB; USPAT;	S41	3	("5877927").URPN.	USPAT	OR	ON	2006/07/03 13:56
S44 3 ("5559659" "6434061" "6552886").PN. S45 0 ("6965503").URPN. S46 23 (disable disabling) near2 (circuit device circuitry) and (RC near2 delay RC near2 timer RC near2 detection RC near2 circuit) and ESD S47 4 ("5255146" "5400202" "5463520" "5528188").PN. SA6 0 ("6965503").URPN. US PGPUB; US PGPUB; OR ON 2006/07/05 13:58 U AT OR ON 2006/07/05 14:05 C T T DB US PGPUB; OR ON 2006/07/05 14:05 C T T DB US PGPUB; OR ON 2006/07/05 14:05 C T T DB US PGPUB; OR ON 2006/07/05 14:19 US PGPUB; OR ON 2006/07/05 14:19 US PGPUB; OR ON 2006/07/05 14:19	S42	569		USPAT; USOCR; EPO; JPO; DERWENT;	OR	1000	1
USC CR; EPO; JPO; DERWENT; IBI1_TDB	S43	133	S42 and (reset override)		OR	ON	2006/07/05 13:56
S44 3 ("5559659" "6434061" "6552886").PN. S45 0 ("6965503").URPN. S46 23 (disable disabling) near2 (circuit device circuitry) and (RC near2 delay RC near2 timer RC near2 detection RC near2 circuit) and ESD S47 4 ("5255146" "5400202" "5463520" "5528188").PN. EPO; JPO; DERWENT; IS11_TDB US.PGPUB; OR ON 2006/07/05 13:58 UV. AT OR ON 2006/07/05 13:58 CR ON 2006/07/05 14:05 S47 4 ("5255146" "5400202" "5463520" "5528188").PN. S48 OR ON 2006/07/05 14:19 UV. AT OR ON 2006/07/05 14:19							
S44 3 ("5559659" "6434061" "6552886").PN. US PGPUB; UT AT; UT OCR ON 2006/07/05 13:58 OR ON 2006/07/05 13:58 US PGPUB; UT AT; UT OCR ON 2006/07/05 13:58 OR ON 2006/07/05 14:05 OR ON 2006/07/05 14:05 OR ON 2006/07/05 14:19 OR ON 2006/07/05 14:19				EPO; JPO;			
S45 0 ("6965503").URPN. S46 23 (disable disabling) near2 (circuit device circuitry) and (RC near2 delay RC near2 timer RC near2 detection RC near2 circuit) and ESD S47 4 ("5255146" "5400202" "5463520" "5528188").PN. ULAT OR ON 2006/07/05 13:58 CR ON 2006/07/05 13:58 OR ON 2006/07/05 14:05 S47 4 ("5255146" "5400202" "5463520" "5528188").PN. ULAT OR ON 2006/07/05 14:05 CR ON 2006/07/05 14:19						l i l sad	
S46 23 (disable disabling) near2 (circuit device circuitry) and (RC near2 delay RC near2 timer RC near2 detection RC near2 (S44	3	("5559659" "6434061" "6552886").PN.	UC⊬AT;	OR	ON	2006/07/05 13:58
S46 23 (disable disabling) near2 (circuit device circuitry) and (RC near2 delay RC near2 timer RC near2 detection RC near2 (S45	0	("6965503").URPN.	UL AT	OR	ON	2006/07/05 13:58
S47 4 ("5255146" "5400202" "5463520" "5528188").PN. US-3GPUB; US T; U T; U TR	S46	23	near2 delay RC near2 timer RC near2 detection RC near2	U.T; U.R; JPO; WENT;	OR	ON	
C40 C (#F000000) 10000	S47	4	(" 5255146" "5 400202" "5463520" "5528188").PN.	US-PG PUB; UC . T;	OR	ON	2006/07/05 14:19
, , , , , , , , , , , , , , , , , , ,	S48	6	("5825603").URPN.	U AT	OR	ON	2006/07/05 14:19

S49	10	("5345357" "5745323" "5783851" "5825603" "5877927" "5907464" "6034552" "6118323" "6249410" "6369994").PN.	US PGPUB; US AT; USOCR	OR	ON	2006/07/05 14:23
S50	16	("4423431" "4819047" "4989057" "5124877" "5311391" "5489792" "5528188" "5567968" "5591992" "5610790" "5625214" "5683918" "5708288" "5726844" "5729419" "5811857").PN.	US PGPUB; UTPAT; U OCR	OR	ON	2006/07/05 14:25
S51	4	("6369994").URPN.	USPAT	OR	ON	2006/07/05 14:45
S52	1	("5825603").PN.	UC PGPUB;	OR	OFF	2006/07/05 14:45